

Troubleshooting

(Collet chucks)

	Details of the trouble	Cause	Pulled out of holder. Unable to attach fast to spindle or holder in case of MT shank.
1	Poor machining accuracy	<p>① Poor concentricity of drill (regrinding error)</p> <p>② Poor accuracy of cutting tool. (diameter, runout or shapness etc.)</p> <p>③ Large runout of tool</p> <p>④ Improper cutting conditions</p>	<p>① •Replacement with new tool •Center drilling before making drill holes</p> <p>② Tool replacemen</p> <p>③ •Refer to "poor runout accuracy" below. •Use "R-Zero" holder.</p> <p>④ •Check recommended cutting conditions by tool maker. •Lower feed per tooth</p>
2	Chattering	<p>① Chattering from holder's resonance</p> <p>② Cutting resistance is too small in comparison with holder's rigidity.</p> <p>③ Cutting resistance is too high in comparison with holder's rigidity.</p> <p>④ Bending moment is too large.</p> <p>⑤ Low taper contact of interface • Poor taper contact from expanded spindle nose • Dust, scratch or dent in the taper part or end face (in the case of two-face contact)</p> <p>⑥ Mischoice of retention stud</p> <p>⑦ Expansion of BT shank because of over-tightening retention stud.</p>	<p>① Shift rotation speed (more than 10%)</p> <p>② Revision of cutting conditions (Increase cutting resistance.) a : Higher feed rate or lower rotation (Approx. 20%) b : Higher cutting depth</p> <p>③ •Revision of cutting conditions (Decrease cutting resistance.) a : Higher rotation speed or lower feed rate (Approx. 20%) b : Lower cutting depth •Use bigger tool holder</p> <p>④ •Use bigger tool holder •Shorter tool projection length •Shorter holder length</p> <p>⑤ •Regrinding and correction of machine spindle •Cleaning of taper and end face (in the case of two-face contact) , touching up of scratch or dent.</p> <p>⑥ Use designated retention stud for the machine</p> <p>⑦ Keep recommended torque valuefor tightening retention stud.</p>
3	Tool is pulled out during operation	<p>① Insufficient tightening of cap nut</p> <p>② Insufficient tightening of cup nut from rotor ring's malfunction</p> <p>③ Insufficient tightening of cup nutbecause of increased friction. (Collapse of collet is not big enough.)</p> <p>④ Cutting resistance is too large. (Pull out of tool because of pestle-like movement.)</p> <p>⑤ Insufficient rigidity of holder</p>	<p>① •Keep recommended torque value for tightening cap nut. •Use torque wrench.</p> <p>② Replacement of cap nut</p> <p>③ Apply oil (grease) on the thread part.</p> <p>④ Cuting resistance should be lowered. a : Shorter tool protruding length b : Higher rotation or lower feed rate (Approx. 20%) c : Lower cutting depth</p> <p>⑤ •Use bigger tool holder. •Recommendation of milling chuck or shrinker chuck instead.</p>

4	<p>Poor runout accuracy during cutting</p> <p>Guidelines AA grade collet 20 micrometers and more at 4D</p>	<p>① Poor chucking accuracy of collet</p> <p>② Dust seizing in collet insertion area</p> <p>③ Scratch or dent in holder ID</p> <p>④ Scratch or dent on collet ID and OD</p> <p>⑤ Insufficient chucking length</p> <p>⑥ Poor accuracy of tool</p> <p>⑦ Dust seizing in cap nut thread</p> <p>⑧ Malfunction of rotor ring of cap nut (Rotor ring will not rotate smoothly.)</p> <p>⑨ Elasticity of preset screw is lost.</p> <p>⑩ Expansion of BT shank because of over-tightening retention stud.</p> <p>⑪ Deteriorated accuracy of tool interface <ul style="list-style-type: none"> • Large runout (2 micrometers and above) of spindle ID or end face (in the case of two-face contact) • Dust, scratch or dent on taper area or end face (in the face of two-face contact) </p>	<p>① <ul style="list-style-type: none"> • Replacement of collets • AA grade collet should be used. </p> <p>② Cleaning of collet insertion area</p> <p>③ <ul style="list-style-type: none"> • Replacement of holder or tool • Touching up of area in question (rubbing off with sand paper #1000 and above) • Correction (grinding) by NT TOOL is not possible. • Ask NT for repair. </p> <p>④ Replacement of collets</p> <p>⑤ Keep minimum insertion length. (collet ID length must be filled.)</p> <p>⑥ Replacement of tools</p> <p>⑦ Cleaning of thread part, applying grease</p> <p>⑧ <ul style="list-style-type: none"> • Cleaning of cap nut (so that rotor ring will rotate smoothly) • Replacement of cap nuts </p> <p>⑨ <ul style="list-style-type: none"> • Chuking too with its tail detached from holder body • Replacement of preset screws </p> <p>⑩ Keep recommended torque value for tightening retention stud.</p> <p>⑪ <ul style="list-style-type: none"> • Regrinding or correction of machine spindle • Cleaning of taper and end face (in the case of two-face contact), touching up of scratch or dent </p>
5	<p>Cap nut is loosened during operation</p>	<p>① Insufficient tightening of cap nut</p> <p>② Insufficient tightening of cap nut because of increased friction in the thread part</p>	<p>① <ul style="list-style-type: none"> • Keep recommended torque value for tightening cap nut. • Use torque wrench. </p> <p>② Apply oil (grease) on the thread part after cleaning it.</p>
6	<p>Cap nut will not rotate be loosened generate noise</p>	<p>① Seizing of foreign matters in thread area</p> <p>② Seizing of thread because of over-tightening cap nut.</p> <p>③ Increased friction of thread part of cap nut due to insufficient lubrication</p>	<p>① Cleaning of thread part</p> <p>② <ul style="list-style-type: none"> • Keep recommended torque value for tightening cap nut. • Use torque wrench. </p> <p>③ Apply oil (grease) on the thread part.</p>
7	<p>Collet will not be removed from holder body</p>	<p>① Wrong installation of collet</p>	<p>① Secure installation of collet in cap nut before tightening it.</p>
8	<p>Coolant leakage</p>	<p>① OH or C type collet is not in use.</p> <p>② Insufficient tool chucking length</p> <p>③ Tool shank diameter is too small. (Smaller than collet ID by 0.2mm and more.)</p>	<p>① Selection of FDC-OH or FDC-C</p> <p>② Keep minimum insertion length of tool (collet's ID length must be filled.)</p> <p>③ Selection of right collet for tool shank diameter</p>

9	Preset screw will not move smoothly.	① Seizing of dust on thread part	① Cleaning of threda part after removing preset screw
---	--------------------------------------	-------------------------------------	--